

MEAL IST

- 1. ARTICLE 349 WAS FLOWN ON 8 JUNE WITH INSTRUMENTED ENGINE 610399 AND FUEL CONTROL 22277.
- 2. A NORMAL CLIMB WAS MADE FOLLOWED BY AN EMERGENCY CLIMB AND ANOTHER NORMAL CLIMB.
- 3. ENGINE CHARACTERISTICS WERE VERY GOOD. THERE WAS NO INDICATION OF THE ENGINE PARAMETER TRANSIENTS EXPERIENCED WHEN THIS ENGINE FUEL CONTROL COMBINATION WAS PRÉVIOUSLY FLOWN.

  THE ONLY KNOWN CHANGE TO THIS UNIT SINCE THE LAST FLIGHT WAS THE CHANGE OF THE ACCESSORY GEAR BOX.
- 4. A SLIGHT ENGINE VIBRATION WAS NOTED, HOWEVER, IT WAS NOT CONSIDERED UNACCEPTABLE BY THE PILOT.
- 5. A REFLIGHT WILL BE CONDUCTED WITH THIS COMBINATION ON 9 JUNE. THE FUEL LOAD WILL BE INCREASED TO 1045 GALLONS TO PERMIT EVALUATION OF THE ENGINE CHARACTERISTICS DURING A SLOWER CLIMB.

END OF MESSAGE

SECRET

EROUP 1 EXCLUDED FROM SUITO-MATIO COMMORAUMO MMD DEULADDIFICATION

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.